

Manhole Inspection Summary

Manhole # S13EE_004MH

Printed On: 8/6/2009

Page 1 of 3

Inspection ☒ **Is Incomplete** Rating: **2) Good**

Record Plat: **13EE** Node: **004** Status: **Not Found**

Insp Date: **2/4/09 2:44 PM**

Incomplete Comments

Cannot Access - Buried - Manhole Existing Confirmed by As-built

Crew: **ADS4**
Inspector: **ADS3**
Firm: **ADS**

Location Address: **REAR OF 2913 PRESSTMAN ST** Cross Street: **BLOOMINGDALE RD**

Manhole Type: **Terminal** Location: **Alley** Ground Conditions: **Dry**
☐ Prev. Rehab Weather: **Dry** Subject To Ponding: **None**
Comments **SEARCHED IN ALLEY WITH METAL DETECTOR FOR TERMINAL NODE. SEARCHED IN VECTOR OFF OF DOWNSTREAM NODE 036 AND CANNOT LOCATE. BELIEVE DOES NOT EXIST.**

Cover Shape: Diameter: (in.) Length: (in.) Dist A/B Grade: (in.)
Type: **Sanitary** Condition: Cover Material: **Cast Iron**
Properties: ☐ Bolted ☐ Vented ☐ Water Tight ☐ Water Tight Insert

Frame Offset: (in.) Condition: ☐ Sound ☐ Cracked ☐ Leaks

Chimney / Frame Adjustment ☐ Exists Material: ☐ Parged Height: (in.)
Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☐ Loose Brick ☐ Deteriorated
Infiltration: ☐ None ☐ Joint ☐ Cracks ☐ Mortar ☐ Roots ☐ Wall

Corbel Material: ☐ Parged Type:
Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☐ Loose Brick ☐ Deteriorated
Infiltration: ☐ None ☐ Joint ☐ Cracks ☐ Mortar ☐ Roots ☐ Wall

Barrel Material: ☐ Parged
Shape: Diameter: (in.) Length: (in.)
Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☐ Loose Brick ☐ Deteriorated
Infiltration: ☐ None ☐ Joint ☐ Cracks ☐ Mortar ☐ Roots ☐ Wall

Bench ☐ Exists Material: ☐ Parged
Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☐ Deteriorated ☐ Leaks ☐ Debris

Channel Material: ☐ Parged
Channel Exposure: **Fully Open** Junc Dist: **0** nearest .5 ft. Azimuth:
Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☐ Deteriorated ☐ Leaks ☐ Debris

Steps Count: Missing: ☐ Corroded

Surcharge ☐ Evidence Of Surcharge Depth: (ft.) ☐ Active Surcharge Present

